

# SOIL CONTROL LAB

42 HANGAR WAY  
WATSONVILLE  
CALIFORNIA  
95076  
USA

Villa Del Monte Mutual Water Co.  
P.O. Box 862  
Los Gatos, CA 95031  
Attn: Mike Miller

Work Order #: 9040886  
Reporting Date: May 1, 2019

## Bacteriological Examination of Water for Coliform Organisms

Date Received: Water sample(s) received April 30, 2019  
Project # / Name: None / Del Monte Way Main Repair  
Water System #/Name: 4400595 VILLA DEL MONTE MWC  
Sampling Type: Special Sampling Period: April 2019  
Sampler's Name: David Montion / GGM Water  
Matrix: Drinking Water

<u>Sample Identification</u>	<u>Sampling Date</u>	<u>Sampling Time</u>	<u>Residual Chlorine (mg/L)</u>	<u>Total Coliforms</u>	<u>E. coli</u>
23479 Sunset Drive	04/30/19	09:30	3	Absent	Absent

Date/Time Analyzed: 04/30/19 17:10  
Method of Analysis: SM 9223 B

CA ELAP Certificate #1494 (This identifies our Laboratory to the Health Department)

*Mike Galloway*