

# SOIL CONTROL LAB

42 HANGAR WAY  
WATSONVILLE  
CALIFORNIA  
95076  
USA

Villa Del Monte Mutual Water Co.  
P.O. Box 862  
Los Gatos, CA 95031  
Attn: Mike Miller

Work Order #: 9090791  
Reporting Date: September 27, 2019

## Bacteriological Examination of Water for Coliform Organisms

Date Received: Water sample(s) received September 26, 2019  
Project # / Name: None / One Time - Repair  
Water System #/Name: 4400595 VILLA DEL MONTE MWC  
Sampling Type: Special Sampling Period: September 2019  
Sampler's Name: Gary MacKenzie / GGM Water  
Matrix: Drinking Water

<u>Sample Identification</u>	<u>Sampling Date</u>	<u>Sampling Time</u>	<u>Residual Chlorine (mg/L)</u>	<u>Total Coliforms</u>	<u>E. coli</u>
23596 Skyview Terrace	09/26/19	12:15	2.8	Absent	Absent
23600 Skyview Terrace	09/26/19	12:41	3.1	Absent	Absent

Date/Time Analyzed: 09/26/19 16:45  
Method of Analysis: SM 9223 B

CA ELAP Certificate #1494 (This identifies our Laboratory to the Health Department)

*Mike Galloway*